

## Message

**From:** Crowley Engineering [crowley@eastchicago.com]  
**Sent:** 10/11/2016 3:59:28 PM  
**To:** Alcamo, Thomas [alcamo.thomas@epa.gov]; Carla Morgan [cmorgan@eastchicago.com]  
**Subject:** RE: USS Lead Site: Zone 3 2016 Remediation as of 10 am, 10/11/16

Tom:

As a follow up to our call this morning, Rocky confirmed that a water service line was repaired in Zone 3 at Personal Address / Ex. 6 on 10/5/16.

Please let us know as soon as you can regarding the soil conditions at the Elevated Water Storage Tank where there is an active service line leak onto Chicago Ave.

Thanks,  
Greg

---

**From:** Alcamo, Thomas [alcamo.thomas@epa.gov]  
**Sent:** Tuesday, October 11, 2016 10:05 AM  
**To:** Crowley Engineering; Carla Morgan  
**Subject:** FW: USS Lead Site: Zone 3 2016 Remediation as of 10 am, 10/11/16

---

**From:** Drexler, Timothy  
**Sent:** Tuesday, October 11, 2016 9:47 AM  
**To:** omarrero@eastchicago.com  
**Cc:** Alcamo, Thomas <alcamo.thomas@epa.gov>; Byron Hartman <b.hartman@erllc.com>; Adler, Kevn <adler.kevin@epa.gov>; Fischer, Timothy <Fischer.Timothy@epa.gov>; Short, Thomas <short.thomas@epa.gov>; Mitchell, James <mitchell.james@epa.gov>; Turner, Kevin <turner.kevin@epa.gov>; Kimble, Jeffrey <kimble.jeffrey@epa.gov>  
**Subject:** RE: USS Lead Site: Zone 3 2016 Remediation as of 10 am, 10/11/16

Hi: Below is today's status.

Personal Address / Ex. 6

**Personal Address / Ex. 6**

The steps in the remediation process are, in order:

- 1) Pre-excavation survey, 2) excavation, 3) excavation survey, 4) place fill, 5) place topsoil, 6) Post-fill survey, 4) restoration (sod and replacing plants, bricks, etc.).